PLANTINO ENGINEERED TIMBER FIRST FLOORS OFFERS THE FOLLOWING WARRANTIES:

Your selected flooring will be covered by one or more of the below warranties.

25 YEAR STRUCTURAL INTEGRITY WARRANTY

For more information contact www.hurfordflooring.co.nz

information



WARRANTY PROVIDED BY



This warranty is effective for purchases made after 1st August 2017.



warranty

The original purchaser of Hurford Flooring engineered flooring in New Zealand is offered the following warranty, effective for purchases made after 1st August 2017.

25 Year structural integrity warranty

The manufacturer warrants its product in its original manufactured condition to be free from defects in material and workmanship, including dimension, lamination and assembly.

Notes

Timber flooring will continue to expand and contract during normal seasonal temperature and humidity changes. The product, when properly installed, may experience slight expansion, contraction and separation between boards, which is normal. If minor separation does occur, it is not covered by this warranty. Expansion gaps should be installed as required.

Timber may naturally experience minor checking (cracks). This is not covered by this warranty.

Being manufactured from a natural material, colour variations can occur between batches of the same species. Colour and appearance can also be affected by exposure to ultraviolet light and oxygen.

Product thought to be defective by the installer should be returned to your dealer for inspection and possible replacement prior to installation. Installation implies acceptance of the appearance related claims, relating to features visible at purchase, once the products are installed.

If a flooring product from Hurford Wholesale Ltd. should fail to meet the Terms of the Warranty, Hurford Wholesale Ltd. and the manufacturer, at its option, will either supply a replacement product from the current range, parts to repair or replace the defective product, or refund the purchase price of the defective product prorated over the remaining life of this limited warranty. A minimum of 10% of the total installed surface area must be affected for the warranty to apply.

This warranty is exclusive. It covers the repair or replacement of defective materials only. It does not cover labour costs. Installation of the replacement products will be at the buyer's expense. The above remedy is the customer's only and is an exclusive remedy for claims under this warranty.



WARRANTY PROVIDED BY





varranty

Conditions

The manufacturer will honour claims under this warranty, only if all of the following conditions are satisfied:

- The covered person/company must provide proof of date of purchase, original purchase price and that they are the original purchaser. They must also demonstrate the floor is at the original installation site.
- At all times between purchase and installation, the flooring must be properly stored according to installation instructions.
- This warranty applies to interior construction only.
- The flooring must be installed in accordance with the manufacturer's installation instructions. Relative humidity in the area of use must be maintained within a range of 30% to 70%.
- Hurford Flooring must be maintained in accordance with the manufacturer's recommendations.
- The manufacturer must receive written notice within 30 days after discovery of any claimed defect or failure covered under this warranty. The manufacturer must be given 60 days following notice to inspect the product to confirm any failure. Written notice should be sent to Hurford Wholesale Ltd. The manufacturer or its representatives must be given the opportunity to inspect the floor prior to any repair or alteration.

Warranty exclusions

The manufacturer's warranty does not cover the following:

- Indentations, scratches, damage caused by negligence or accident, water ingress, insects, animals, high heeled or spiked shoes, urine and high traffic areas.
- Failure to follow the manufacturer's written engineered timber floor installation instructions, including protecting the floor from subfloor moisture.
- Exposure to excessive heat, sunlight or improper humidity in the environment.
- Improper maintenance, insufficient protection or misuse.
- Improper alterations to the original manufactured product. Alterations or repairs to the manufacturer's original product will void any and all warranties.
- Changes in colour or appearance due to full or partial exposure to sunlight, weather, ageing or refinishing.
- Failure due to structural changes in the subfloor, settling of the building or an uneven subfloor that has not been adequately levelled (+/- 3mm over 1000mm).

Warranty disclaimers

The foregoing is in lieu of all other warranties expressed or implied, including but not limited to, the implied warranties of merchantability and fitness for a particular purpose, except as covered by Common Law. The manufacturer shall not be liable for loss of use or any other incidental or consequential costs, expenses or damages incurred by the original purchaser.



WARRANTY PROVIDED BY





Maintaining your floor

Your engineered floor is designed with low maintenance in mind. Follow these simple steps to achieve many years of enjoyment from your floor:

- Sweep or vacuum as often as necessary to remove any loose dirt or grit.
- Use protective mats at all exterior entrances. Do not use rubberbased mats as the rubber may leach into the floor.
- Use felt protectors under heavy pieces of furniture.
- Never slide or roll furniture or appliances across your floor. Protect the surface if using a trolley to move heavy objects.
- Spiked heels or shoes in need of repair can severely damage your floor.
- Steam mops must not be used. If a spill occurs, soak up the bulk liquid promptly.
- Always follow the maintenance as listed below and only use approved cleaning products.
- Maintain relative humidity levels between 30% and 70%.

MAINTENANCE OF OSMO HARDWAX OIL

Daily/ Weekly Cleaning

<u>Osmo Wash & Care</u> - Used as a cleaner for weekly or bi-monthly cleaning, Wash and Care cleans and nourishes the floor in one step.

Quarterly Maintenance

From time to time, your Hurford Flooring flooring can look tired, this means it needs refreshing. For private households, generally this is first necessary after some months.

Osmo Liquid Wax Cleaner regenerates the protective oilwax layer and your floor retains its special shine.

Rejuvenation

For high traffic areas or to give your floor a total refresh, Osmo Maintenance Oil can be used to bring back your floor to the original finish level.

The protective surface of your floor can be renewed when the floor starts to show signs of wear. This can be done at any time without needing to sand the old finish. This is a huge advantage over lacquered wooden surfaces.

For further information on Hurford Flooring products, please visit our website at www.hurfordflooring.co.nz or call us on 0800 HURFORD



WARRANTY PROVIDED BY



